

CONSUMER INFORMATION FOR PORCH FLOORING

For installation suggestions, contact the distributor or manufacturer, or visit www.SouthernPine.com.

Porch flooring can provide decades of service, but even the highest grades of this wood, properly protected and used, may exhibit some of the characteristics shown below. These are naturally occurring in wood products, and unavoidable.

Below are natural characteristics of Southern Yellow Pine flooring **an *NOT* covered under any warranty*** (expressed or implied) from the manufacturer or distributor.

- Warping (lumber may twist, bow, or cup)
- Paintability of the floor
- Color consistency, either before or after painting
- Shrinking or swelling of the wood (depending on ambient moisture, wood products experience dimensional change)
- Cracking or splitting
- Buckling or sagging
- Mold or mildew growth

*** Other factors that void warranties include, but are not limited to:**

- Improper installation (flooring must run perpendicular to the walls of the structure)
- Incorrect fastening (fasteners or procedure)
- Installation on any sub-floor such as plywood
- Not allowing proper acclimation of lumber prior to installing
- Installation on wet floor joists
- Inadequate moisture barrier under porch
- Inadequate ventilation
- Improper slope of the porch
- Use is an exposed application

**VISIT: www.SouthernPine.com
(for installation guidelines)**

